



## WEEKLY SUMMARY REPORT

<b>PROJECT NO.:</b>	2476.0001Y002	<b>WEEKLY REPORTING PERIOD:</b> Monday July 7, 2016 through Sunday July 10, 2016
<b>PROJECT:</b>	CFAC Phase I Site Characterization	
<b>LOCATION:</b>	Near Columbia Falls, Montana	

### SUMMARY OF WORK COMPLETED

- Sands Surveying was onsite on July 5, 2016 to survey all new monitoring wells
- Roux Associates personnel gauged all new monitoring wells and accessible existing monitoring wells
- Roux Associates personnel downloaded water level data from six pressure transducers deployed around the Site

### SUMMARY OF WORK PLANNED FOR NEXT WEEK / ANTICIPATED SCHEDULE CHANGES

- Planned
  - Resume drilling and installation of water table and deep monitoring wells
  - Complete clearing of vegetation and grading for access to South Percolation Ponds
  - Complete remaining soil borings in South Percolation Ponds if accessible
  - Resume collection of incremental soil samples in operational grid area
- Modifications
  - No modifications to schedule

### HEALTH AND SAFETY NOTES

- Roux Associates personnel reviewed job safety analyses for gauging and surveying

### OTHER NOTES

- No other notes

Prepared By Mike Ritorto Of Roux Associates, Inc.